YAESU
Radio Communications
YAESU MUSEN CO., LTD.
4-8-8 Nakameguro, Meguro-ku, Tokyo 153-8644, Japan
Tel : 81-(0)3-5725-6122 · Fax : 81-(0)3-5725-6205

August 15th, 2000

Federal Communications Commission
Authorization and Evaluation Division,
7435 Oakland Mills Road
Columbia, MD 21045
USA

Re: FT-817 (FCC ID: K66FT-817)

Gentlemen:

The scanner receiver equipment meets the requirements of the FCC Rules, 15.121(a).

Compliance is achieved through the following methods:

> The scanner receiver in this equipment is incapable of tuning, or readily being altered, by the User to operate within the frequency bands allocated to the Domestic Public Cellular Telecommunications Service in Part 22. Blocking of the cellular frequencies is implemented in the firmware of the unit's main control central processing unit (CPU). Coverage of 824 – 849 MHz and 869 – 894 MHzis completely blocked, since it is done in the microprocessor, and cannot be re-enabled by any user-accessible procedure, including diode, resistor, or jumper changes, nor by connection of any external device such as a personal computer, nor by installation of any "special" enabling semiconductor device.

Sincerely,

YAESU MUSEN CO., LTD.

Mr. Tomiro Ohmoto
General Manager of Export Department